

Notifiable incident

Incident ID [5668](#)

Duty holder: INPEX Operations Australia Pty Ltd
Facility/Activity: Ichthys Venturer
Facility type: Floating production storage and offloading facility

Incident details	
Division	Occupational Health and Safety
Notification type	Incident
Incident date	03/11/2018 06:30 AM (WST)
Notification date	03/11/2018 06:31 AM (WST)
NOPSEMA response date	03/11/2018 08:21 AM (WST)
Received by	[REDACTED]
Nearest state	WA
Initial category type <i>(based on notification)</i>	Dangerous Occurrence
Initial category <i>(based on notification)</i>	Damage to safety-critical equipment
3 Day report received	05/11/2018
Final report received	30/11/2018
All required data received	
Final category type <i>(based on final report)</i>	Dangerous Occurrence
Final category <i>(based on final report)</i>	Damage to safety-critical equipment
Brief description	OHS-DSCE-Fire Water Foam Skids - Failure to meet performance standard
Location	Process deck
Subtype/s	Facility integrity
Summary <i>(at notification)</i>	Operator advised that during 6 monthly function testing of fire water foam skids, solenoids and actuators failed to operate remotely from the CCR as per design on 8 out of 30 skids. This was a breach of performance standard F6.5 (Active Fire Protection Standard). All skids have since been returned to service.
Details <i>(from final report)</i>	<p>Operator advised that during 6 monthly function testing of fire water foam skids, solenoids and actuators failed to operate remotely from the CCR as per design on 8 out of 30 skids. This was a breach of performance standard F6.5 (Active Fire Protection Standard). All skids have since been returned to service.</p> <p>During routine maintenance (function testing) of the Firewater Foam Skids, solenoid and actuator failures occurred on 8 out of 30 foam skids which would have resulted in foam activation not being able to be activated from the Central Control Room (CCR). Therefore S060-AH-PST-10043 Active Fire Protection – FPSO Performance Standard was not met - section F.6.5 - Foam valves and associated components shall be functional.</p>
Immediate cause/s	Solenoid failure / Actuator failure (sticking)
Root cause/s	
Root cause description	The casual factors identified to date include: 1. Trunnion ball valve with instrument air actuating system not suitable for quick release application. 2. Contamination/corrosion in both actuating air line and foam line.

Duty inspector recommendation	
Date	05/11/2018
Duty inspector	
Recommendation	Do not conduct Major Investigation
Reasoning	Does not meet MI threshold based on information received
Supporting considerations	

Major investigation decision	
Date	05/11/2018
Decision	Do not conduct Major Investigation
Reasoning	Does not meet MI threshold based on information received
Supporting considerations	

Non-major investigation review and recommendation	
Date	
Inspector	
Risk gap	Moderate
Type of standard	Established
Initial strategy	Investigate

Recommended follow up strategy	
Recommended strategy	Investigate
Supporting considerations	Consequence - serious, failure of an MAE control. Benchmark likelihood - remote. Potential likelihood increases to possible, due to loss of remote control of the deluges. Established standard - as per SoV. Relevant incidents - deluge solenoid failures - RMS 5586, 5591, 5598, 5630

Non-major investigation decision	
Date	06/11/2018
RoN	
RoN review result	Agree with recommendation
Strategy decision	Investigate
Supporting considerations	

Associated inspection	
Inspection ID	1794