

Please check the following boxes if applicable to this report			Nil Incident Report: <input type="checkbox"/>	Final report for this activity: <input type="checkbox"/>	
Titleholder name:	Woodside	Titleholder business address:	240 St Georges Terrace Perth WA 6000	Title of environment plan for the activity:	Persephone Drilling and Subsea installation Activities Environment Plan
Activity type: (e.g. drilling, seismic, production)	Drilling and Completions	Month, Year:	September 2016	Facility name and type: (e.g. MODU, Seismic Vessel, FPSO)	Ocean Apex MODU
Contact person:	██████████	Email:	██████████@Woodside.com.au	Phone:	██████████
Incident date	All material facts and circumstances (including release volumes to environment if applicable)	Performance outcome(s) and/or standard(s) breached	Action taken to avoid or mitigate any adverse environmental impacts of the incident	Corrective action taken, or proposed, to stop, control or remedy this incident	Action taken, or proposed, to prevent a similar incident occurring in future
14/9/2016	Operations to pretension anchor number 1 and 2 were commencing and at the respective winch houses identified fairlead #5 had failed. During this failure, the fairlead pin and grating had been dropped to seabed. At the time of the incident the MODU was in a safe handling area.	EPO 22 No significant incidents of dropped objects to the marine environment in Operational Areas during the Petroleum Activities Program	Operations were halted and stability and safety confirmed. The rig was moved, remaining in a safe handling zone.	The objects were recovered on 16/9/2016.	<ol style="list-style-type: none"> Review installation of fairleader External third party tech service to review fairleader Review the incident with all crews.