

Recordable Environmental Incident Monthly Report

Due Date: By the 15th day of the following month.

Send completed form to: submissions@nopsema.gov.au via

secure file transfer at

https://securefile.nopsema.gov.au/filedrop/submissions

Reference: Regulation 26B

Please check the following boxes if applicable to this report			Nil Incident Report:	Final report for this activity:	
Titleholder name:	Woodside Energy Limited and Mitsui Exploration and Production Ltd	Titleholder business address:	Woodside Plaza 240 St Georges Terrace, Perth WA 6000	Title of environment plan for the activity:	Exmouth Sub -Basin Gas Well Program
Activity type: (e.g. drilling, seismic, production)	Drilling	Month, Year.	June 2014	Facility name and type (e.g. MODU, Seismic Vessel, FPSO)	Deepwater Millennium (MODU)
Contact person:		Email:	⊕woodside.com.au	Phone:	
Incident date	All material facts and circumstances (including release volumes to environment if applicable)	Performance outcome(s) and/or standard(s) breached	Action taken to avoid or mitigate any adverse environmental impacts of the incident	Corrective action taken, or proposed, to stop, control or remedy this incident	Action taken, or proposed, to prevent a similar incident occurring in future

16/62014	A bunkering hose leaked approximately 20mL of fuel to the sea during bunkering activities.	No loss of hydrocarbons to the marine environment within the operational area from refuelling during the drilling program.	No mitigation measures were undertaken based on volume of hydrocarbon release.	Bunkering was suspended immediately, connection investigated and tightened to ensure an effective seal.	and are to review bulk hose configuration for hydrocarbon transfers and evaluate the type of connections in place. In addition, the length of the bulk hoses will be adjusted to 45m to allow for more movement and to reduce the risk of stress on hose connections. A WECO connection either side of the dry-break coupling was installed. The Recommended Rig Practice was evaluated and now includes the requirement for all hoses to be brought onboard and visually inspected for wear spots, stretch marks, parting of the hose (visible threads) and damage from twisting, prior to each bunkering operation.
----------	--	---	--	---	---

Note 1: As at 28 February 2014, amendments to the Offshore Petroleum and Greenhouse Gas Storage (Environment) Regulations changed from environmental performance objective to environmental performance outcome. If you are reporting against an EP accepted under the old Regulations please report against the environmental performance objective for that activity.

Note 2: This form may be submitted in conjunction with the 'Injuries and Fatalities – Monthly Summary Report' Form available at www.nopsema.gov.au

Privacy Notice

NOPSEMA collects your contact details for the purpose of administering the OPGGSA and associated regulations. NOPSEMA will not use or disclose your personal information for any other purpose without your consent, unless it is required or authorised by law, or relates to NOPSEMA's enforcement activities. Your personal information may be disclosed to the following organisations, entities or individuals:

- individuals who make a request under the Freedom of Information Act 1982
- the Australian National Audit Office and other privately-appointed auditors
- NOPSEMA's legal advisors.